



	<b>Service Letter SL 5</b>	EB - Nr. I - EC 34
--	--------------------------------	-----------------------

## Planning Information

### Affected Parts:

Screws Part No. MS 35265-65/ A-1635-70 and Washer Part No. AN 960-10

### Affected Propellers:

All Hydraulic Constant Speed Propellers.

### Reason:

Replacing of this screws by corrosion resistant screws with higher strength in hydraulic constant speed propellers.

### Description:

Components introduced by this Service Letter are incorporated into the MT-Propeller Manuals E-220, E-373, E-519, E-520, E-571 latest Issues.

### Affected Publications:

Overhaul Manual E-220, Hydraulically Controlled Variable Pitch Propeller MTV-5-(), -6-(), -9-(), -11-()  
-12-(), -14-(), -15-(), -16-(), -21-(), -22-(), -25-()  
Overhaul Manual E-373, Hydraulic Constant Speed Propeller MTV-2-(), MTV-3-()  
Overhaul Manual E-519, Reversible Hydraulically Controlled Variable Pitch Propeller MTV-5-1-,  
-9-, -12-, -14-, -16-1-, -25-2-, -27-1-()-R(M)  
Overhaul Manual E-520, Reversible Hydraulically Variable Pitch Propeller MTV-25-1-()-R(M)  
Overhaul Manual E-571, Hydraulically Controlled Variable Pitch Propeller

## Material Information

Screw Part No. MS 35265-65 replaced by Screw NAS 1352C3H12  
Screw Part No. A-1635-70 replaced by Screw NAS 1352C3H24  
Washer Part No. AN 960-10 replaced by Washers Part No NAS 1149C0363R

Freigabe MPL <i>Clearance MPL</i> Datum: May 12, 1999 <i>Date</i>	Ausgabe <i>Edition</i> vom: May 12, 1999 <i>Date</i>	Blatt Nr. 1 <i>Page No.</i> von 1 <i>of</i>
--	---	--