mt-propeller
Entwicklung GmbH

Airport Straubing-Wallmühle
94348 Atting / Germany
Telefon 49-(0)9429-9409-0
Telefax 49-(0)9429-8432
E-mail: sales@mt-propeller.com

	Service Letter **SL 17B**	DOA No. EASA.21J.020

Important Information

Affected Parts:
Replacement of MTV-9 / -12 / -14 / -15 hubs and additional required material for serial numbers up to 97xxx.

Affected Propellers:
MTV-9 / -12 / -14 / -15

Reason:
Propellers on which the hub must be replaced during repair and overhaul,

Description:
A.m. Propeller models must be assembled with new hub and additional parts as described below, according the Overhaul Manual E-220 (ATA 61-12-20)

Affected Publications:
Overhaul Manual E-220 (ATA 61-12-20)

Material Information

MTV-9-( ):

2 Check nuts	A-893-A
1 Spring guide	A-1271-81
1 Front plate	A-1245
1 Piston guide rod	A-252-C x = 188 y = 146

MTV-12-( ):

2 Check nuts	A-893-A
1 Spring guide	A-1271-72
1 Front plate	A-1245
1 Piston guide rod	A-252-C x = 174 y = 132

MTV-14-( ):

2 Check nuts	A-893-A
1 Spring guide	A-1271-72
1 Front plate	A-1245
1 Piston guide rod	A-389-B x = 174 y = 132

MTV-15-( ):

2 Check nuts	A-893-A
1 Spring guide	A-1271-81
1 Front plate	A-917-C
1 Piston guide rod	A-391-D x = 167 y = 145