



	Service Letter SL 2	EB - Nr. I - EC 34
--	--------------------------------	-----------------------

Planning Information

Affected Materials:

Grease **Aeroshell 6**

Affected Propellers:

All Constant Speed Propellers.

Reason:

Replacing of Aeroshell 6 since Feb. 04, 1999.
Aeroshell 6 caused in some special cases grease leakage problems.

Description:

Components introduced by this Service Letter are incorporated into the MT-Propeller Manuals E-220, E-250, E-310, E-373, E-519, E-520, E-571 latest Issues.

Affected Publications:

Overhaul Manual E-220, Hydraulically Controlled Variable Pitch Propeller MTV-5-(), -6-(), -9-(), -11-()
-12-(), -14-(), -15-(), -16-(), -21-(), -22-(), -25-()

Overhaul Manual E-250, Electrically Controlled Variable Pitch Propeller MTV-1-(), -7-(), -10-(), -17-(),
-18-() -20-()

Overhaul Manual E-310, Mechanische Verstellpropeller MTV-24-()

Overhaul Manual E-373, Hydraulic Constant Speed Propeller MTV-2-(), MTV-3-()

Overhaul Manual E-519, Reversible Hydraulically Controlled Variable Pitch Propeller MTV-5-1-,
-9-, -12-, -14-, -16-1-, -25-2-, -27-1-()-R(M)

Overhaul Manual E-520, Reversible Hydraulically Variable Pitch Propeller MTV-25-1-()-R(M)

Overhaul Manual E-571, Hydraulically Controlled Variable Pitch Propeller

Material Information

Aeroshell 5 is used instead of Aeroshell 6

Freigabe MPL <i>Clearance MPL</i> Datum: May 12, 1999 <i>Date</i>	Ausgabe <i>Edition</i> vom: May 12, 1999 <i>Date</i>	Blatt Nr. 1 <i>Page No.</i> von 1 <i>of</i>
--	---	--