



	Service Letter SL 7A	EB - Nr. JAA-LBA.NJA.009
--	---------------------------------	-----------------------------

Planning Information

Affected parts:

Screws M3x10 for the mounting support between electric pitch change motor and gear box.

Affected Propellers:

All Electric Constant Speed Propellers.

Reason:

The mounting with screws M3x10 is not sufficient, therefore we use M3x12 since July 1998.

Material Information

Replacing of screws M3x10 by screws M3x12.

<i>Clearence MPL</i>	<i>Edition</i>	<i>Page No. 1</i>
<i>Date: March 05, 2003</i>	<i>Date: March 05, 2003</i>	<i>of 1</i>