



	Service Letter SL 8	EB - Nr. I - EC 34
--	--------------------------------	-----------------------

Planning Information

Affected parts:

Resin Isamet R4 + Hardener 41.

Affected Propellers:

All natural composite blades

Reason:

From October 7, 1999 Resin Isamet R4 is replaced by Resin A20 and Hardener 41 is replaced by Hardener B 20 because of higher building capability and better treatability. Additionally the torsional stiffness of the blade is increased.

Material Information

Mixing ratio of the new material is 100:60.

Freigabe MPL <i>Clearance MPL</i> Datum: Nov 29, 1999 <i>Date</i>	Ausgabe <i>Edition</i> vom: Nov 29, 1999 <i>Date</i>	Blatt Nr. 1 <i>Page No.</i> von 1 <i>of</i>
--	---	--