



	Service Letter SL 9A	EB - Nr. JAA-LBA.NJA.009
--	---------------------------------	-----------------------------

Planning Information

Affected parts:

Blade Bearings A-317, A-233, A-004

Affected Propellers:

All variable pitch propellers

Reason:

From 31.01.2000 blade bearings A-317-A are replaced by A-317-B

From 01.02.2000 blade bearings A-233-A are replaced by A-233-B

From 01.04.2001 blade bearings A-004-E are replaced by A-004-F

Because of easier installation, less abrasion and less friction.

Freigabe MPL <i>Clearance MPL</i> Datum: 27.08.2001 <i>Date</i>	Ausgabe <i>Edition</i> vom: 27.08.2001 <i>Date</i>	Blatt Nr. 1 <i>Page No.</i> von 1 <i>of</i>
--	---	--