

SERVICE BULLETIN Governor on Lake LA-4-200-() airplanes No. 22 Initial Issue	DOA No. EASA.21J.020
---	-------------------------

To: All owners/operators of Lake LA-4-200-() airplanes using variable pitch propellers of MT-Propeller type MTV-12-B-C-R(M)/CRLD188-119a.



Subject: Compatibility of MT-Propeller Governors P-980-16 (28 VDC system) or P-980-11 (14 VDC system) according MT-Propeller Service Bulletin No. 14, latest revision.

Type affected: MTV-12-B-C-R(M)/CRLD188-119a propellers which are installed on Lake LA-4-200-() according LBA STC No. SA1230 or FAA STC No. SA00156BO.

Accomplishment: MT-Propeller P-980-16 or -11 governor shall be installed on new installations.
MT-Propeller P-480-10 governors can be retained on existing installations.

Reason: Introduction of an additional certified governor model

This Service Bulletin has been approved according the procedures established for the EASA-certified Design Organization No.: EASA.21J.020.

Checked / Approved: Head, Office of Airworthiness  Martin Albrecht Date: 13 March 2007	Edition :  Wolfgang Schwefel Date: 13 March 2007	Page 1 of 1
---	--	-------------